

Scooter paint job

Before doing any painting, you will need to take off most of the old pain. First of all you will need to wash the parts with soap and water and let them dry. Use a medium fine grade (220 grit) of sandpaper and work until it's smooth.




After sanding, don't forget to wash it again so the surface is dust free.



Your next step would be to dry your body for around 45 minutes to an hour (depending on the air temperature).



Next you'll need to suspend your body parts like this in a closed area.



This is the color that I will use, a blue metallic. You can see that you also need primer and clear gloss to do a good job.



Put the primer on first. Stay about 2 feet away from the body. Wait 10 minutes between coats (2 or 3 coats will be needed)



After the final coat, wait an extra 15-20 minutes. Lightly sand as needed (to make a smooth surface) and apply your chosen paint.



This is what I get after my first coat. Don't forget to shake often so that the paint flows smoothly. Wait around 10 minutes between coats.



After 3 coats this is what I get. Let dry and lightly sand as needed.



After applying 3-5 coats, you should get a nice uniform finish.



For a nice finish put gloss on the body part and you'll get that deep shiny look. Don't let the paint dry too much or else the gloss won't stick well. So wait about 5 minutes between coats. Lightly sand as needed.



Let dry and now you are done!!

